

## IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of: ) Examiner: Timothy J. Henn  
: :  
Akitoshi Yamada, et al. ) Group Art Unit: 2622  
: :  
Appln. No.: 10/541,381 ) Confirmation No.: 6303  
: :  
Filed: January 29, 2004 ) Patent No.: 7,289,141B2  
: :  
For: IMAGE SUPPLY DEVICE, ) Issued: October 30, 2007  
RECORDING APPARATUS, :  
RECORDING SYSTEM, AND ) December 17, 2008  
CONTROL METHOD THEREFOR :  
:

Commissioner for Patents  
P.O. Box 1450  
Alexandria, VA 22313-1450

REQUEST FOR CERTIFICATE OF CORRECTION UNDER RULE 323

Sir:

It is respectfully requested that a Certificate of Correction be issued by the U.S. Patent and Trademark Office due to errors which appear in the printed patent as a result of mistakes, and mistakes of a clerical, typographical, or minor character, which were not the fault of the U.S. Patent and Trademark Office. A Certificate of Correction form (Form PTO-1050) is enclosed.

The \$100.00 fee for the Certificate of Correction is being paid electronically. However, the Commissioner is authorized to charge any underpayment or credit any overpayment to Deposit Account No. 06-1205.

Patentees' undersigned attorney may be reached in our Washington, D.C. office by telephone at (202) 530-1010. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

/Warren E. Olsen/  
Warren E. Olsen  
Attorney for Patentees  
Registration No.: 27,290

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
Facsimile: (212) 218-2200  
WE0/kag  
2101465v1

UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 7,289,141 B2

DATED : October 30, 2007

INVENTOR(S) : Akitoshi Yamada, et al.

Page 1 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 2

Line 1, "provided with" should read --provided--.

Line 18, "provided with" should read --provided--.

COLUMN 6

Line 47, "Dvice Status" should read --Device Status--.

COLUMN 7

Line 66, "generation" should read --generation of--.

COLUMN 8

Line 30, "interrupted," should read --been interrupted,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 7,289,141 B2

No. of add'l. copies  
@ 30¢ per page



UNITED STATES PATENT AND TRADEMARK OFFICE  
CERTIFICATE OF CORRECTION

PATENT NO. : 7,289,141 B2

DATED : October 30, 2007

INVENTOR(S) : Akitoshi Yamada, et al.

Page 2 of 2

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

COLUMN 13

Line 14, "statue" should read --status--.

Line 47, "statue" should read --status--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO  
30 Rockefeller Plaza  
New York, New York 10112-3800  
(212) 218-2100 - Telephone  
(212) 218-2200 - Facsimile

PATENT NO. 7,289,141 B2

No. of add'l. copies  
@ 30¢ per page

